

Usdrowski, Sarah L SWL

From: Singleton, Bob [SINGLETON@adeq.state.ar.us]
Sent: Thursday, September 06, 2007 9:46 AM
To: Usdrowski, Sarah L SWL
Subject: Dumping debris in Fourche Creek

Sarah,

Eric Fleming is out this morning so I will relay the information he gave me yesterday. The creek site is at the west end of Raines Trail off Crystal Valley Road (accessible by either Highway 5 or Colonel Glenn) in southwest Little Rock. Hugh Daniels Trucking was contracted to haul and dump the material from a bridge demolition. Jeff Cole Construction is evidently the company doing the work. I will send the google photo along also.

Bob

9/6/2007



Raines Road

Jonathan Road

Raines Cove

ARK00147H



Google

Image State of Arkansas
© 2007 Europa Technologies
© 2007 Tele Atlas

Pointer 34°41'00.49" N 92°28'42.04" W elev 376 ft Streaming 100% Eye alt 6331 ft

CESWL-RO (1145b)

MEMORANDUM FOR RECORD

DATE: September 12, 2007

SUBJECT: Mark Carter - #18493

1. I called Mr. Mark Carter to inquire whether he had discharged bridge demolition debris within Fourche creek. He mentioned that he did authorize a contractor to discharge "rip-rap" adjacent to his bridge crossing to re-nourish rip-rap that had washed down from previous high flow events. He did acknowledge that the rip-rap did have some rebar in it and intended to have this cleaned out.
2. I told Mr. Carter I'd likely give him until the end of next week to clean up any unacceptable discharge in terms of either discharge location or composition of discharge material. I mentioned that he is not authorized to discharge within Fourche creek outside of the permitted area.
3. I recommend a site inspection following the week of September 10-14.

Bradley Myers
Project Manager

REPORT OF POSSIBLE VIOLATION/RAMS DATA SHEET

Action No.: 18493 Section: _____ Project Manager: Mgers

Project Name: _____ Project Office: _____

Date Signed: _____ Date Received: 09/06/07 Related Nos.: _____

Applicant's/Violator's Name: Hugh Daniels Trucking (or) Jeff Cole Construction
Last First Middle

Address: _____

Phone: _____
City State Zip

Basin: _____ Waterway: Fouche Lake Mile/Bank: _____

Lake: _____ UTMs: N _____ E _____ Authority: _____

Status: _____
Code Began End Code Began End Code Began End

Work Reported by: Bob Singleton - APCA Phone: 682-0645

Address: _____

Source Code: _____
City State Zip

Description of Work: Dumping bridge demolition debris into Fouche Lake.

Location of Work: See attached map/aerial

Little Rock
City

Pulaski
County

AR
State

Comments: _____

Completed by: _____

M4PRRBCM - **ORM_REGULATOR** - SWL Role Preferences Logout

Home

Search

SWL-2003-18493

Help

Home Folder Waters JDs **NONCOMPLY** Map Impacts Indicators Letters Documents Contacts Regulators Comments

Successfully Updated All Information.
Successfully Finalized.

DA Number: SWL-2003-18493 (CARTER, MARK)

Applicant: No Applicant Found

Non-Compliance Activity Resolution

1. Begin Date 06-Sep-2007
2. Discovery Method External Report (e.g., Neighbor, Agency, etc.)
3. Jurisdictional Authority Section 404
4. Waters Name Site 1 OTHER WATERS SWL-2003-18493
5. Closure Method Accepted Restoration
6. End Date 31-Oct-2007
7. Comments
It was reported that bridge demolition debris was dumped into Fourche Creek on Mr. Mark Carter's property as the site of his Fourche Creek crossing. >10/31/2007 update- It appears that Mr. Carter removed the reported rebar from the rip-rap that was placed for renourishment. Though there was more rip-rap discharged than we would have preferred, I recommend no further action because any further disturbance to the creek would likely result in more harm than good.

Optional Items

District-Specific Data Elements (DSDE)

No District-Specific Data Elements Have Been Added To This Action.

Reopen Options

Reopen as New Version - Please Select -

Commands

Reopen

Cancel

Feedback (Page 34)

M4PRRBCM - ORM_REGULATOR - SWL Role Preferences Logout

Home

Search

SWL-2003-18493

Help

Home Folder SITEVISIT Waters JDs Map Impacts Indicators Letters Documents Contacts Regulators Comments

Successfully Updated All Information.
Successfully Finalized.

DA Number: SWL-2003-18493 (CARTER, MARK)

Applicant: No Applicant Found

Site or Field Visit (Inspection)

1. Begin Date 06-Sep-2007
2. Date of Visit 31-Oct-2007
3. Agency Notified []
4. Associated Water Site []
5. Closure Method In Compliance With Permit Conditions (Compliance Procedure)
6. End Date 31-Oct-2007
7. Comments
The additional rip-rap placed approximately at the mid-points of the road crossing was seen. The reported rebar that was mixed in with the rip-rap had been removed subsequent to the call by the Corps on September 12, 2007. Though this is more material discharged than the Corps would have preferred, I recommend no further enforcement action at this time because further disturbances to the stream would likely result in more harm than good.

Optional Items

District-Specific Data Elements (DSDE)

No District-Specific Data Elements Have Been Added To This Action.

Reopen Options

Reopen as New Version - Please Select -

Commands

Reopen

Cancel

Feedback (Page 54)